



Lifting Requirements:

- 1. Use all lifting points.
- 2. A spreader bar must be used to keep vertical force on lifting tackle.

Failure to use each lifting point, along with spreader bars and/or neglecting proper lifting procedures may lead to property damage, injury, or death.

UNIT WEIGHT LISTED ON U1 UNIT DRAWING.



FORKS MUST EXTEND ALL THE WAY THROUGH UNIT WHEN LIFTING WITH FORK LIFT

	SCALE:	ENGINEERING APPROVED BY:	QUALITY CONTROL APPROVED BY:	DRAWN BY: M.L.
	DATE: 05/02/2024			
	SUB-TITLE: WMT-GLY-LIFTING			DRAWING NUMBER: WMT-SEC-GLY-RIGGING